





250



WICHTIG - FÜR SPÄTERE VERWENDUNG
AUFBEWAHREN - SORGFÄLTIG LESEN

AVIS - Ces instructions doivent être sauvegardées
Pour utilisation future - Les instructions doivent
être suivies


IMPORTANTE, conservar estas instrucciones
para futuro uso. Siga estas instrucciones atentamente

VIGTIGT - Samvejledningen skal opbevares
i arkiv til senere brug - Skal gennemlæses nøje

NOTICE - These instructions must be saved
for future use - Instructions must be followed







TEILCHECKLISTE
LISTE DE CONTROLE
LISTADO DE CONTROL
TJEKLISTE
CHECK LIST



Réf. /No.	Réf. /Art.	Qty. /Stck. /Quantité	Size / Maß / Dimension (mm)	Qty. /Stck. /Quantité	
1	56XX000025001	1	1200X600X175		✓
2	56XX000025002	4			




TEILCHECKLISTE - LISTE DE CONTROLE - LISTADO DE CONTROL- TJEKLISTE - CHECK LIST



Réf./No.	Réf./Art.	Qty./Stck./Quantité	
A	983204	24	
B	982578	4	
C	982579	4	
D	69003	1	
E	982580	1	
F	982581	1	

24 - A	4 - B	4 - C	1 - D	1 - E	1 - F
 M6x12 mm (M6 x 1/2")				 M4	 M6








X4



3 1-D



4



5-5